

Technical Bulletin

Product:	2WIN
Date:	2021/06/25 (June 25, 2021)
Bulletin number and title:	30 – New software release 5.5.4
Issue has a relevance for the device safety:	NO
Field Safety Corrective Action:	Not required
Issue has a relevance for the device performance:	YES
Reason:	<ul style="list-style-type: none"> - New 2WIN software version (bug fixing) - New Operator Manual
S/N affected:	All
Scope of notice:	All Distributors/Other
Service time:	Less than 5 minutes for software update procedure
Service parts:	Full-system-5.5.4
Description:	See next pages
Required action:	Update recommended
Hardware compatibility:	All
For further info please contact:	<p>Adaptica srl</p> <p>Via San Marco, 9/h – 35129, Padova (PD), Italy</p> <p>Tel: +39 049 773 968</p> <p>Fax: +39 049 097 0901</p> <p>Email: support@adaptica.com</p>

Summary of bugs fixed in 2WIN SW version 5.5.4

- Fixed bug on CR app's PDF image display. This bugfix improves 2WIN performances.

IMPORTANT NOTE: it is not possible to downgrade 2WIN's software to a previous version.

Summary of modifications introduced in Operator Manual version 9.7

- Updated software configuration version.
- Updated revision number.

Known bugs

- Image not displayed on PDF report of CR app.