

Technical Bulletin

Product:	2WIN
Date:	2020/12/10 (December 10, 2020)
Bulletin number and title:	28 – New software release 5.5.2
Issue has a relevance for the device safety:	NO
Field Safety Corrective Action:	Not required
Issue has a relevance for the device performance:	YES
Reason:	<ul style="list-style-type: none"> - New 2WIN software version (bug fixing) - New KALEIDOS App version (bug fixing) - New Operator Manual
S/N affected:	All
Scope of notice:	All Distributors/Other
Service time:	Less than 5 minutes for software update procedure
Service parts:	Full-system-5.5.2, 2winbt_v38(1.3.12.3)-release.apk
Description:	See next pages
Required action:	Update recommended
Hardware compatibility:	All
For further info please contact:	<p>Adaptica srl Via San Marco, 9/h – 35129, Padova (PD), Italy Tel: +39 049 773 968 Fax: +39 049 097 0901 Email: support@adaptica.com</p>

Summary of bugs fixed in 2WIN SW version 5.5.2

- Fixed bug on i2c bus drivers. This bugfix improves 2WIN performances.

IMPORTANT NOTE: it is not possible to downgrade 2WIN's software to a previous version.

Summary of bugs fixed in KALEIDOS App version 1.3.12.3

- Name and date of birth fields inverted in the PDF report when using Repeat function
- Compatibility issues on Android 10 tablets

IMPORTANT NOTE: it is not possible to downgrade KALEIDOS App to a previous version.

Summary of modifications introduced in Operator Manual version 9.5

- Updated tablet specifications for the compatibility with KALEIDOS App. Updated list of recommended tablet models (§14)
- Updated information about 2WIN and 2WIN-S packaging labels (§8.4)
- Updated important notes on 2WIN and 2WIN-S batteries (§9.9)
- Updated 2WIN and 2WIN-S cleaning instructions (§19.1)

Known bugs

- Impossible to open the PDF report using 2WIN App WiFi on Android 10 tablets. The PDF report can be opened from the tablet's folder: Internal Storage\TUBEWIN.