

Master - Technical Bulletin

Product:	2WIN
Date:	2019/11/20 (November 20, 2019)
Bulletin number and title:	25 – New software release 5.4.2
Issue has a relevance for the device safety:	NO
Field Safety Corrective Action:	Not required
Issue has a relevance for the device performance:	YES
Reason:	<ul style="list-style-type: none"> - New software version - New operating manual
S/N affected:	All
Scope of notice:	All Distributors/Other
Service time:	Less than 5 minutes for software update procedure
Service parts:	full-system-5.4.2
Description:	See next pages
Required action:	Update recommended
Hardware compatibility:	All
For further info please contact:	<p>Adaptica srl Via San Marco, 9/h – 35129, Padova(PD), Italy Tel: +39 049 773 968 Fax: +39 049 097 0901 Email: support@adaptica.com</p>

Summary of changes and bugs fixed in SW version 5.4.2

- New update for 2WIN BT application, including:
 - o Available Bluetooth devices search included in the 2WIN BT APP
 - o Patient data management in compliance with GDPR (General Data Protection Regulation)
 - o New measurement results window layout
 - o PDF footer customization
- Stability of Bluetooth connection improved
- New operator manual

IMPORTANT NOTE: it is not possible to downgrade 2WIN's software to a previous version.